Date 7-3-71
Incident Number 9!18:6
County Cook
City Chicago Heighto
Site name Roadura, Cypneso
Site address 2000 Rinoch, Highia

0310455034 Cook
Roadway Expres
Compliance



Dear Underground Storage Tank Owner/Operator,

Enclosed are the Corrective Action Response and Report Requirements. All owners/operators of a leaking underground storage tank (LUST) must follow the requirements described in this packet pursuant to Part 731 Underground Storage Tanks/Title 35: Environmental Protection Subtitle G, Chapter I, Subchapter d.

The first written response to the Illinois Environmental Protection Agency is due within twenty (20) days of the discovery of the LUST. When submitting this first report, include the Incident number found at the top of this page. All correspondence must be submitted in duplicate.

You must also submit within twenty (20) days of the discovery of the LUST the carbon copy of the Contingency Plan. The original must be posted in a prominent place for your employees at the LUST site.

Should you have any questions while completing the response and report requirements, contact the IEPA for assistance (refer to enclosed regional map). You may also want to refer to the Agency's **Guidance Manual for Petroleum-Related LUST Cleanups in Illinois** for an indepth look at the LUST program and the responsibilities of a tank owner/operator.

Sincerely,

Harry A. Chappel, P.E., Manager

Leaking Underground Storage Tank Section

Division of Land Pollution Control

cc. LUST Legal Counsel Division File Region File

Generator Identification Number

A facility initiating cleanup of a regulated substance from a LUST, including petroleum, will need a Generator I.D. Number. The tank owner/operator (generator) must complete and submit to the IEPA the Illinois Generator Identification Number Request Form and the Authorization Statement (enclosed). Questions regarding completion of the form may be directed to Permit Section, Administrative Support Unit at 217/782-6762. Generator I.D. Number requests are normally processed within four weeks upon receipt of a properly completed form. Once a Generator I.D. Number is assigned, the form will be returned to the tank owner/operator via UPS delivery. A supply of manifests and a Manifest Order Form will be enclosed for the tank owner/operator's use.

Manifests

When removing special waste from a LUST site, a licensed special waste hauler must transport the waste. An IEPA manifest must accompany the transporter. The manifest is a six (6) part document which lists the specific waste and its quantity, the generator of the waste, the hauler who has accepted the load, and the name of the receiver.

Treatment, Storage and Disposal Facilities

Prior to the off-site transportation or handling of contaminated material from a LUST site, the tank owner/operator must contact a facility which is authorized to accept these contaminated materials. For a listing of the Treatment, Storage and Disposal facilities in your area, call the Permit Section, Solid Waste Unit at 217/782-6762.

Corrective Action Response and Report Requirements (enclosed)

All tank owners/operators of a LUST must complete the response and report requirements. The first written response to the IEPA is due within twenty (20) days of the discovery of the release.

Contingency Plan (enclosed)

This form should be completed immediately upon discovery of a LUST. The original must be posted in a prominent place for your employees at the LUST site. The carbon copy must be submitted to the IEPA within twenty (20) days of the discovery of a LUST.